



## AES January 28, 2015 Site Visit Photo-Documentation



Confidential/Enforcement Sensitive

**José A. Rivera**  
Senior Environmental Engineer



# Highlights on the Facility Walkthrough

- *Walkthrough to check on pending implementation of BMPs, Sampling Points, Yards, Aggremax<sup>™</sup> Pile, Coal Pile, Limestone Dome, and Ponds*
- *Crushed stone re-application observed throughout*
- *Water mounted-tank truck sprinkling water on internal roads*
- *Mechanical Sweeper (not as effective as water application)*
- *Inlet Protection*







# Stabilization / Crushed Stone







# Housekeeping







# Ponds







# Sampling / Discharge Point 001







# Sampling / Discharge Point 002







# Sampling / Discharge Point 003







## CCR Management / Aggremax Pile

- *Aggremax pile is significant lower than when was last seen during the December 2, 2014 visit*
  - *150,000 tons removed between June 2014 and November 2014*
  - *More than 260,000 tons removed in 2014*
  - *More than 220,000 tons removed between November 2014 and January 2015*
  - *Completed installation and operation of 9 sprinklers for Aggremax pile water irrigation at a \$350,000 cost.*
  - *Sprinklers were observed in operation during the Walkthrough.*
  - *Water Tank-Mounted Truck also use to wet the pile and other areas*





# Aggremax Pile







# Water Sprinklers System







# Pending BMPs

- Stabilization of certain areas within the coal pile runoff pond hydrological areas







# Pending BMPs

- Housekeeping – Diesel Tank Secondary Containment

